



Cell 93421 75592

Sri Kalabyrava Electricals

Down Bazaar Road, Yelahanka, Bangalore - 560 064.

Ref:

Date 12/05/17

To
Assistant Executive Engineer
Yelahanka Sub Division,
BBMP, Bengaluru-64.

Dear Sir,

Name Of Work:- Drilling of Borewell and providing pipe line to existing Borewell at
Maruthinagara and surrounding area ward No-01.

Maruthinagara 3rd Main Near Bhuvaneshwari Yuvakara Sanga.

SI No	Description (RR No YP _____)	Amount
01	Application Fees for BESCOM	100.00 ✓
02	Meter Charges	1889.75 ✓
03	Contractor Charge for getting Service	2700.00
04	Deposit to Bescom	8160.00 ✓
05	Miscellaneous	-
Total Amount		12,849.75 10149

In enclosing the Original BESCOM receipts, I am Requested your kind self to reambers the same.

Thanking You,

gc



**SRI KALABHYRAVA
ELECTRICALS**
Govt. Licenced
Electrical Contractors
Muniyamma Compound
Down Bazaar Road, Yelahanka
BANGALORE 560 064



Sri Kalabyrava Electricals

Cell : 93421 75592

Down Bazaar Road, Yelahanka, Bangalore - 560 064.

Ref:

Date 12/05/17

To
Assistant Executive Engineer
Yelahanka Sub Division,
BBMP, Bengaluru-64.

Dear Sir,

Name Of Work:- Drilling of Borewell and providing pipe line to existing Borewell at
Maruthinagara and surrounding area ward No-01.

Maruthinagara 1st Main 17th Cross Road

SI No	Description (RR No YP _____)	Amount
01	Application Fees for BESCOM	
02	Meter Charges	100.00 ✓
03	Contractor Charge for getting Service	1889.75 ✓
04	Deposit to Bescom	2700.00
05	Miscellaneous	8160.00 ✓
Total Amount		12,849.75

In enclosing the Original BESCOM receipts, I am Requested your kind self to reambers the
same.

Thanking You,

gz

Chit
**SRI KALABHYRVA
ELECTRICALS**
Govt. Licenced
Electrical Contractor
Muniyamma Compound
Down Bazaar Road, Yelahanka
BANGALORE 560 064

ಸಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh

Mob : 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref :

Date :

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP

Address Yelchanka 1st Main 17th Cross

Masuthinagar

Location Near Sree Shakti temple

Topography

Soil Type Hard Soil

Rock Type Black Rock.

Nos.

RECOMMENDATIONS

Depth 1000 - 1100

Casing 168 - 180

Yield 3"

Aquifers 3 1/2"

Remarks —

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Kavitha Singh

Water Diviner

ಸಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref. :

Date : 14/04/17

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP

Address 3rd Main Maruthinagara

-lelanka

Location Adjacent to 4th Cross

Topography

Soil Type Hard Soil

Rock Type Black.

Nos.

RECOMMENDATIONS

Depth 900 - 1000

Casing 150 - 170

Yield 2"

Aquifers 2"

Remarks Shited Type.

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Kavitha

Water Diviner

ಸಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref. :

Date : 20/03/12

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP

Address Tank Bund Road Venkatala

Location Near Venkatala lake

Topography

Soil Type Loose soil

Rock Type White Rock

Nos.

RECOMMENDATIONS

Depth 1000 - 1200

Casing 180 - 200

Yield 2"

Aquifers 2 1/2"

Remarks — Loose Soil

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Kavitha
Water Diviner

92



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : **116**

Date : 12/04/17

1. Customer's Name and Address : AEE YELAHANKA
with Telephone No. _____
2. Well Location : 3rd Main MARUTHNAGAR.
3. Total Well Depth / Drilled in Ft. : 980 ft
4. Casing Erected in Ft. : 170 - 190 ft
5. Water Struck at the Depth of : 640 - 800 ft
6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Rock Soil
8. At the Depth of : 1000 ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

For **VINAYAKA ENTERPRISES**

Manager / Proprietor

SRI BAALAMURUGAN BOREWELLS

Hennur-Bagalur Road, opp. Vijaya Bank, Kothanur, Bangalore
Mob. : 9845020536, 9901920004



WORK REPORT

To AEE VELAMANKA 2 nd main 5 th Cross Venkatalu			No. : 145	
			Date : 20/03/17	
S.No	Particulars	Rft	Water Yield	Remarks
1.	Size of the Borewell	6 1/2		
2.	Total Depth of the Borewell	940		
3.	MS Casing Erected	185		
4.	1st Water Source at the Depth	720	1/2"	
5.	2nd Water Source at the Depth	900	1/2"	
6.	3rd Water Source at the Depth	930	1/2"	
7.	4th Water Source at the Depth	-	-	
8.	If any Silt, Boulders at the Depth	- No -	-	
9.	Nature of Water	Normal	-	
10.	Motor Pump to be used	Yes	-	
11.	Any other Remarks	-	-	
12.	Total Yield of the Borewell		1 1/2"	

Thanking You

Party's Signature

Yours faithfully,
For Sri Baalamurugan Borewells

Manager / Proprietor



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL
COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 116

Date : _____

1. Customer's Name and Address : AEF YELAHANKA
with Telephone No. _____
2. Well Location : 1st MAIN 17th CROSS MARUTHINAGAR
3. Total Well Depth / Drilled in Ft. : 1100 Ft
4. Casing Erected in Ft. : 162 - 180 Ft
5. Water Struck at the Depth of : 480 Ft - 840 - 960 Ft
6. Total Yield (Measuring method "V" Norch : 2 1/2 INCHES / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ROCK SOIL
8. At the Depth of : 1120 Ft
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

gr

For VINAYAKA ENTERPRISES

Raj Kumar
Manager / Proprietor